PRE-BID REPLIES TO BIDDER QUERIES

Tender: Hiring of Services for MDPE Laying and Associated Works (LMC) for RJ GA

Tender No.:GASONET/C&P/GSL/PE PNG/RJ/2026-2027/32

Sr. No.	Tender	Page No.	Bidder's Query	Gasonet Reply
1			1. HDD Laying Rate -The difference between HDD with casing and without casing is only Rs. 50. In practical work, casing involves much higher cost, so we request you to kindly review this difference.	Ref: SOR Line Item no. 2.1 & 2.3 Rate (Refer revised SOR), HDD with casing rates are ₹701.5/m (63 mm) and ₹799/m (125 mm).
2			Provide details regarding the liaisoning amount, as it is currently omitted.	Liaisoning charges are already included & merged in other line items, no separate payment shall be made. Liaisoning activities shall remain within the contractor's scope.
3			HSE GI Section -The rate for riser is given as Rs. 10. This seems very low on a per riser basis. We request you to kindly make it per meter or revise the rate.	Ref: SOR Line Item no. 7.1 No change. Safety is a mandatory compliance requirement, not a commercial item, and shall be strictly followed by the contractor.
4			Liasoning - Liasoning and permissions are in contractor 's scope, but no separate rate has been given for it. We request you to kindly add a rate for this.	Liaisoning charges are already included & merged in other line items, no separate payment shall be made. Liaisoning activities shall remain within the contractor's scope.
5			MLC Pipe & Fittings -The SOR for MLC pipe is not clear and details of brass fittings are also not mentioned. Kindly share the complete specification.	Ref: SOR Line Item no. 8.16 MLC pipe and fittings are the free issue material, supplied by the company.
6			CPBG Retention -We request confirmation that the CPBG retention amount will be released after submitting the full Bank Guarantee.	Agreed
7		page no-10-	Reduce the working capital criteria to a maximum of 2-3 Crore.	Refer Corrigendum-1
8			Confirm the rate for the Diamond Cutter.	Not applicable in case of MDPE works.
9			RCC Breaking - RCC breaking is mentioned as 12 inch, but in actual site conditions we never get RCC more than 6 inch. Kindly revise this as per practical site	It is recommended to revise RCC breaking covering 6 inch to 24 inch on same rate 300rs/m.
10			Hard Rock -The rate given for hard rock does not seem correct as per market rates. We request you to kindly revise it.	Not applicable in case of MDPE works.
11			GC Rate -GC rate has not been included at all. Kindly add a rate for the same.	GC rates are included with laying.